

# **REPORT**

Level One Inspection and Testing Services

Meridian Estate Stage 11, Clyde North, Lots 1111 to 1129

Prepared for:

Grosvenor Lodge Pty Ltd

August 2018

Our Ref: 3807351.011.v2

### **Document Control**

Title: Level One Inspection and Testing Services								
Date	Version	Description	Prepared by:	Reviewed by:	Authorised by:			
17-05-18	1	Level One report, 3807351.011.v1	PRS	RHB	TJC			
17-08-18	2	Level One report, 3807351.011.v2	RHB	RHB	TJC			

Grosvenor Lodge Pty Ltd Chadwick Geotechnics Pty Ltd (FILE) pdf

1 сору

### Table of contents

1	Introduction	1
2	Project details	1
3	Geology	2
4	Specification	2
5	Inspection and testing	2
6	Conclusion	3
7	Applicability	4

Appendix A: Density Test Location Plan

Appendix B: Table of field density results

Appendix C NATA endorsed laboratory reports

Appendix D: Controlled fill certificates

### 1 Introduction

This report supersedes report (3807351.011.v1 dated May 2018, Meridian Estate Stage 11, Clyde North, Lots 1120 to 1129). Additional earthworks were undertaken in December 2017 to February 2018 across lots 1111 to 1119, the field testing relating to these earthworks were not reported within the initial Stage 11 report. This reissued report takes the laboratory test results into consideration, resulting in additional residential lots being included within this report.

Chadwick Geotechnics Pty Ltd (Chadwick Geotechnics) was engaged by Grosvenor Lodge Pty Ltd, to provide Level 1 Inspection and Testing services for the earthworks within Stage 11 of the Meridian Estate in Clyde North.

### 2 Project details

The project included the preparation and filling of lot's 1111 to 1129. The specification required the earthworks to be completed under Level 1 Supervision that is, full-time Inspection and Testing of the earthworks. Chadwick Geotechnics were onsite for the duration of the earthworks program.

The approximate location of the site is shown in figure 1 below.



Figure 1: Approximate site location (Image sourced from Nearmaps)

### 3 Geology

Published information<sup>1</sup> shows that the site is underlain by various geologies listed as follows;

- Quaternary Age Unnamed dune deposits Formation (Qd1) comprising of sand, clay and calcareous sand.
- Quaternary Age Unnamed swamp and lake deposits Formation (Qm1) comprising of silt and clay.
- Palaezoic Age Murrindindi Supergroup (Sm) comprising of mudstone and sandstone
   Neogeone Age Baxter Sandstone Formation (Nxx) comprising of sandstone, conglomerate, siltstone and ironstone.

### 4 Specification

A summary of the specification is shown below:

Compaction Requirement	95 % Standard Compaction
------------------------	--------------------------

### 5 Inspection and testing

The inspection and testing of earthworks has been carried out in accordance with AS3798-2007, 'Guidelines on earthworks for commercial and residential developments', with a frequency of field density tests as per a type one project (large scale operation). Compaction control laboratory testing was undertaken in our NATA accredited Dandenong South laboratory in accordance with AS1289 'Methods of Testing Soils for Engineering Purposes'.

Prior to fill being placed the subgrade was inspected. The inspections were performed in accordance with the Level 1 guidelines presented in AS 3798–2007 Section 5.5. No soft spots were encountered during the inspections, and the area was found to be firm and free of vegetation and other deleterious material.

Full time Level 1 Inspection and testing of the filling operations commenced on the 19<sup>th</sup> December 2017 and was completed on the 28<sup>th</sup> February 2018. During this period Chadwick Geotechnics observed the filling works including the supply of material, conditioning of material (moisture conditioning and oversize removal), placement and compaction of the fill.

All fill material was placed in lift sequences and the Chadwick Geotechnics verified that the surface of the stripped area and additional lifts were thoroughly scarified and moisture conditioned prior to placement of additional layers to prevent delamination at the layer interface.

Field density and moisture content testing was carried out using a calibrated nuclear density gauge in accordance with AS 1289.5.8.1. The HILF rapid compaction test was used for peak converted wet density determinations in accordance with AS 1289.5.7.1. Test locations were recorded using a handheld GPS unit. A site plan showing the field density test locations is provided in Appendix A.

A total of twenty three (23) tests were performed during the filling process.

The results show that three (3) tests failed to meet the specification requirements for the project. The earthworks contractor was advised of the tests that failed and the fill relevant to those areas

<sup>&</sup>lt;sup>1</sup> BIBBY, L.M., 2004. Simplified 1: 4 000 000 Geology of Victoria. Geological Survey of Victoria Special Publication. GeoScience Victoria.

was reworked, reconditioned, re-compacted and subsequently retested. The final results show the tests achieved the specification requirements for the project.

A summary table of Hilf density tests is provided in Appendix B and the laboratory test reports and Fill Certificates are provided in Appendix C and D.

### 6 Conclusion

On the basis of our inspections and after considering all test results relating to the project, it is our opinion, so far as it is able to be determined, that:

- The materials used by the earthworks contractor met the geotechnical property requirements of the specification.
- The sourced fill was considered to be natural and clean and suitable for use at the site.
- The fill material placed was tested at a suitable frequency in accordance with AS 3798-2007-Table 8.1 and the results indicate the compacted clay achieved the density requirement of the specification.
- Given the consistent construction practices followed by the earthworks contractor and as witnessed by the Chadwick Geotechnics, combined with the satisfactory verification of test results achieved, it is inferred that areas of the site between test locations were performed to the same standard as those areas that have been tested.

It is our opinion that the earthworks undertaken have been performed in accordance with the requirements of Section 8.2 Level 1 Inspection and Testing AS3798-2007.

### 7 Applicability

This report has been prepared for the exclusive use of our client Grosvenor Lodge Pty Ltd in good faith and in accordance with the Chadwick Geotechnics quality system for the earthworks filling at the site.

This report is based on the nature of the project and the conditions present in, factors affecting the soil at the time of the inspections, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted, and Chadwick Geotechnics is indemnified to the full extent permitted by law in respect of the use of this report where there has been a change in the nature of the project or the conditions on site that may alter or affect the conclusions of this report.

Should you require any further information regarding this report, please do not hesitate to contact the undersigned on (03) 8796 7900.

Chadwick Geotechnics Pty Ltd

Report prepared by:

Authorised for Chadwick Geotechnics Pty Ltd by:

Robert Barden

Timothy Chadwick

© Chadwick Geotechnics Pty Ltd.

Geotechnical Engineer


Other than for the exclusive use of our client Grosvenor Lodge Pty Ltd, no part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise, without the prior written permission of Chadwick Geotechnics Pty Ltd.

**Project Director** 

www.chadwickgeotechnics.com.au

\keysdc\data\rep\live\geo\projects\3807351\11 stage 11\workingmaterial\re issue of level one report august 2018\3807351.011.v2 stage 11 meridian level one report.docx

# Appendix A: Density Test Location Plan



# Appendix B: Table of field density results



## Hilf Summary Table

## 3807351.011.v2 Meridian Estate Stage 11

Report No	Sample No	Date	Test Number	Location [E]	Location [N]	Layer	Density Ratio HILF test (%)	Density Ratio test (%)	Moisture Variation From OMC	Pass / Fail	Remarks
HDR:W17DS02687	10041	19/12/2017	1	355336	5782386	1	96.5		0 wet	Pass	
HDR:W17DS02687	10042	19/12/2017	2	355314	5782374	1	94.5		2 wet	Fail	See Retest 10120
HDR:W17DS02707	10112	20/12/2017	1	355341	5782384	2	99.5		2 dry	Pass	
HDR:W17DS02711	10120	21/12/2017	1	355318	5782372	1	105		2 dry	Pass	Retest of 10042
HDR:W17DS02711	10121	21/12/2017	2	355324	5782393	3	100.5		0 dry	Pass	
HDR:W18DS00007	6	3/01/2018	1	355351	5782418	1	99		0.5 dry	Pass	
HDR:W18DS00013	22	4/01/2018	1	355350	5782417	2	103.5		0.5 dry	Pass	
HDR:W18DS00013	23	4/01/2018	2	355348	5782411	3	100.5		2 dry	Pass	
HDR:W18DS00015	60	5/01/2018	1	355350	5782407	4	100.5		1 dry	Pass	
HDR:W18DS00088	355	16/01/2018	1	355262	5782373	1	98		0 dry	Pass	
HDR:W18DS00088	356	16/01/2018	2	355241	5782378	3	99.5		0.5 dry	Pass	
HDR:W18DS00088	357	16/01/2018	3	355338	5782316	1	100		3 dry	Pass	
HDR:W18DS00088	358	16/01/2018	4	355316	5782349	1	99.5		0.5 dry	Pass	
HDR:W18DS00160	618	23/01/2018	1	355297	5782344	3	102		0.5 dry	Pass	
HDR:W18DS00160	619	23/01/2018	2	355345	5782349	2	96.5		0 wet	Pass	
HDR:W18DS00160	620	23/01/2018	3	355341	5782311	2	103.5		2.5 dry	Pass	



## Hilf Summary Table

## 3807351.011.v2 Meridian Estate Stage 11

Report No	Sample No	Date	Test Number	Location [E]	Location [N]	Layer	Density Ratio HILF test (%)	Density Ratio test (%)	Moisture Variation From OMC	Pass / Fail	Remarks
HDR:W18DS00263	1038	2/02/2018	1	355328	5782345	3	100		1.5 dry	Pass	
HDR:W18DS00387	1390	12/02/2018	1	355331	5782225	1	93.5	Ξ	2 dry	Fail	See Retest 1432
HDR:W18DS00387	1391	12/02/2018	2	355328	5782255	1	100.5	-	0.5 wet	Pass	
HDR:W18DS00403	1432	13/02/2018	1	355327	5782228	1	97.5	-	1 dry	Pass	Retest of 1390
HDR:W18DS00403	1433	13/02/2018	2	355338	5782257	2	95.5	÷	0.5 dry	Pass	
HDR:W18DS00468	1684	16/02/2018	1	355339	5782208	3	98	-	0 dry	Pass	
HDR:W18DS00468	1685	16/02/2018	2	355334	5782260	3	98.5	-	1.5 dry	Pass	
HDR:W18DS00468	1686	16/02/2018	3	355325	5782168	1	98.5	-	0.5 wet	Pass	
HDR:W18DS00496	1760	19/02/2018	1	355339	5782162	2	-	-	-	-	No Laboratory result, tested as MDD, see number 2247
HDR:W18DS00496	1761	19/02/2018	2	355321	5782143	2	96	-	0.5 dry	Pass	
DDR:W18DS00586	2247	19/02/2018	1	355339	5782162	2	-	100	4.5 wet	Pass	MDD of 1760
HDR:W18DS00547	2021	21/02/2018	1	355306	5782172	1	89.5	-	0 dry	Fail	See Retest 2259
HDR:W18DS00591	2259	23/02/2018	2	355283	5782185	1	101.5	-	1.5 dry	Pass	Retest of 2021
HDR:W18DS00662	2549	28/02/2018	1	355235	5782148	1	97		2.5 dry	Pass	

# Appendix C NATA endorsed laboratory reports





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W17DS02687

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

**Project No.:** 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or easurements included in this document are traceable to Australian (national standards

Approved Signatory: M. Robinson

(Senior Technician)

12712 Date of Issue: 28/12/2017
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data				
Sample ID	S17DS-10041	S17DS-10042		
Field Sample ID	1	2		
Date Tested	19/12/2017	19/12/2017		
E	355336	355314		
N	5782386	5782374		
Layer	1	1		
Soil Description	Clay	Clay		
Field and Laboratory Data				
Depth of Test (mm)	150	150		
Depth of Layer (mm)	200	200		
Field Wet Density (t/m³)	1.97	1.94		
Peak Converted Wet Density (t/m³)	2.04	2.06		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	0.0	2.0 wet		
Hilf Density Ratio (%)	96.5	94.5		

$\boldsymbol{c}$	· m	-	0 m	+-
Cc	Ш	ш	en	เอ





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W17DS02707

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

**Project No.:** 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or leasurements included in this document are traceable to Australian/Institute 1

Approved Signatory: M. Robinson

(Senior Technician)

12712 Date of Issue: 28/12/2017
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data				
Sample ID	S17DS-10112			
Field Sample ID	1			
Date Tested	20/12/2017			
E	355341			
N	5782384			
Layer	2			
Soil Description	Clay			
Field and Laboratory Data				
Depth of Test (mm)	150			
Depth of Layer (mm)	200			
Field Wet Density (t/m³)	2.05			
Peak Converted Wet Density (t/m³)	2.06			
Compactive Effort	Standard			
Moisture Variation (%)	2.0 dry			
Hilf Density Ratio (%)	99.5			

$\sim$				
	om	1441		TC
$\mathbf{C}$		ши	CI I	10





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W17DS02711

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or leasurements included in this document are traceable to Australian/pational standards

Approved Signatory: M. Robinson

(Senior Technician)

12712 Date of Issue: 28/12/2017
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data				
Sample ID	S17DS-10120	S17DS-10121		
Field Sample ID	1	2		
Date Tested	21/12/2017	21/12/2017		
E	5782372	5782393		
N	Retest	Layer 3		
	Layer 1			
Soil Description	Clay	Clay		
Field and Laboratory Data				
Depth of Test (mm)	150	150		
Depth of Layer (mm)	200	200		
Field Wet Density (t/m³)	1.99	2.01		
Peak Converted Wet Density (t/m³)	1.90	2.00		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	2.0 dry	0.0		
Hilf Density Ratio (%)	105.0	100.5		

$\boldsymbol{c}$	· m	-	0 m	+-
Cc	Ш	ш	en	เอ





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00007

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or reasurements included in this document are traceable to Australian/national standards.

Approved Signatory: M. Robinson

(Senior Technician)

12712 Date of Issue: 8/01/2018
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data				
Sample ID	S18DS-00006			
Field Sample ID	1			
Date Tested	3/01/2018			
E	355351			
N	5782418			
	Layer 1			
Soil Description	Clay			
<b>Field and Laboratory Data</b>				
Field Wet Density (t/m³)	2.04			
Peak Converted Wet Density (t/m³)	2.05			
Compactive Effort	Standard			
Moisture Variation (%)	0.5 dry			
Hilf Density Ratio (%)	99.0			

<u> </u>	-		 -1-
Ca	144	111	IIS





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00013

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or leasurements included in this document are traceable to Australian/pational standards

Approved Signatory: M. Robinson

(Senior Technician)

12712 Date of Issue: 8/01/2018
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data				
Sample ID	S18DS-00022	S18DS-00023		
Field Sample ID	1	2		
Date Tested	4/01/2018	4/01/2018		
E	5782417	5782411		
N	Layer 2	Layer 3		
Soil Description	Clay	Clay		
Field and Laboratory Data				
Depth of Test (mm)	150	150		
Depth of Layer (mm)	200	200		
Field Wet Density (t/m³)	2.12	2.03		
Peak Converted Wet Density (t/m³)	2.05	2.02		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	0.5 dry	2.0 dry		
Hilf Density Ratio (%)	103.5	100.5		

$\boldsymbol{c}$	· m	-	0 m	+-
Cc	Ш	ш	en	เอ





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00015

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or easurements included in this document are traceable to Australian/national standards.

Approved Signatory: M. Robinson

(Senior Technician)

12712 Date of Issue: 9/01/2018
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data				
Sample ID	S18DS-00060			
Field Sample ID	1			
Date Tested	5/01/2018			
E	355350			
N	5782407			
	Layer 4			
Soil Description	Clay			
Field and Laboratory Data				
Depth of Test (mm)	150			
Depth of Layer (mm)	200			
Field Wet Density (t/m³)	2.09			
Peak Converted Wet Density (t/m³)	2.08			
Compactive Effort	Standard			
Moisture Variation (%)	1.0 dry			
Hilf Density Ratio (%)	100.5			

$\boldsymbol{c}$	· m	-	0 m	+-
Cc	Ш	ш	en	เอ





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00088

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or neasurements included in this document are traceable to Australian/Instituted.

Approved Signatory: M. Robinson

(Senior Technician)

12712 Date of Issue: 30/01/2018
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data					
Sample ID	S18DS-00355	S18DS-00356	S18DS-00357	S18DS-00358	
Field Sample ID	1	2	3	4	
Date Tested	16/01/2018	16/01/2018	16/01/2018	16/01/2018	
E	355262	355241	355338	355316	
N	5782373	5782378	5782316	5782349	
	Layer 1	Layer 3	Layer 1	Layer 1	
Soil Description	Clay	Clay	Clay	Clay	
<b>Field and Laboratory Data</b>					
Depth of Test (mm)	150	150	150	150	
Depth of Layer (mm)	200	200	200	200	
Field Wet Density (t/m³)	1.98	2.00	1.86	2.03	
Peak Converted Wet Density (t/m³)	2.02	2.01	1.85	2.04	
Compactive Effort	Standard	Standard	Standard	Standard	
Moisture Variation (%)	0.0	0.5 dry	3.0 dry	0.5 dry	
Hilf Density Ratio (%)	98.0	99.5	100.0	99.5	

$\sim$				
	om	1441		TC
$\mathbf{C}$		ши	CI I	10





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00160

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

**Project No.:** 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

Approved Signatory: M. Robinson

(Senior Technician)

12712 Date of Issue: 30/01/2018
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data					
Sample ID	S18DS-00618	S18DS-00619	S18DS-00620		
Field Sample ID	1	2	3		
Date Tested	23/01/2018	23/01/2018	23/01/2018		
E	355297	355345	355341		
N	5782344	5782349	5782311		
	Layer 3	Layer 2	Layer 2		
Soil Description	Clay	Clay	Clay		
Field and Laboratory Data					
Depth of Test (mm)	150	150	150		
Depth of Layer (mm)	200	200	200		
Field Wet Density (t/m³)	1.99	2.01	2.07		
Peak Converted Wet Density (t/m³)	1.95	2.08	2.00		
Compactive Effort	Standard	Standard	Standard		
Moisture Variation (%)	0.5 dry	0.0	2.5 dry		
Hilf Density Ratio (%)	102.0	96.5	103.5		

<u> </u>			 . 4 -
	om		те
$\mathbf{c}$	,,,,	ш	LO





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00263

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: CG Request No.:

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations and/or easurements included in this document are traceable to Australian/national standards.

Approved Signatory: J. A. Smith

(Senior Technician)

12712 Date of Issue: 7/02/2018
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample Data				
Sample ID	S18DS-01038			
Field Sample ID	1			
Date Tested	2/02/2018			
E	355328			
N	5782345			
Soil Description	Silty Clay			
Field and Laboratory Data				
Depth of Test (mm)	150			
Depth of Layer (mm)	200			
AS Sieve Size (mm)	19.0			
Field Wet Density (t/m³)	2.01			
Peak Converted Wet Density (t/m³)	2.02			
Compactive Effort	Standard			
Moisture Variation (%)	1.5 dry			
Hilf Density Ratio (%)	100.0			

$\boldsymbol{c}$	· m	-	0 m	+-
Cc	Ш	ш	en	เอ





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00387

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 11

Project No.: 3807351.011

Order No.: CG Request No.: 2708

TRN: Lot No.:

NATA

Accreditation No. 12719
The results of the tests, calibrations

Approved Signatory: D.Henke (Senior Technician)

12712 Date of Issue: 14/02/2018
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Lot Fill

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample ID	S18DS-01390	S18DS-01391		
Field Sample ID	1	2		
Date Tested	12/02/2018	12/02/2018		
E:	355331	355328		
N:	5782225	5782255		
Layer	L1	L1		
Soil Description	Silty Clay	Silty Clay		
Depth of Test (mm)	175	175		
Depth of Layer (mm)	200	200		
AS Sieve Size (mm)	19.0	19.0		
Oversize Wet (%)	0	0		
Field Moisture Content (%)	0.0	0.0		
Field Wet Density (t/m³)	1.91	2.03		
Peak Converted Wet Density (t/m³)	2.03	2.02		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	2.0 dry	0.5 wet		
Hilf Density Ratio (%)	93.8	100.4		

<u> </u>			 4-
	144		ш
Co	ш	ш	





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00403

Accredited for compliance with ISO/IEC 17025 – Testing

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

**Project:** Meridian Estate - Stage 11

Project No.: 3807351.011

Order No.: CG Request No.: 2725

TRN: Lot No.: NATA

Accreditation No. 12719 The results of the tests, calibrations

(Senior Technician) , 14/02/2018 12712 Date of Issue:

Approved Signatory: D.Henke

THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Lot Fill

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Sample ID	S18DS-01432	S18DS-01433		
Field Sample ID	1	2		
Date Tested	13/02/2018	13/02/2018		
E:	355327	355338		
N:	5782228	5782257		
Layer	L1	L2		
	Retest of S-01390 from 12/02/18			
Soil Description	Silty Clay	Silty Clay		
Depth of Test (mm)	175	175		
Depth of Layer (mm)	200	200		
AS Sieve Size (mm)	19.0	19.0		
Oversize Wet (%)	0	0		
Field Moisture Content (%)	0.0	0.0		
Field Wet Density (t/m³)	1.97	1.96		
Peak Converted Wet Density (t/m³)	2.01	2.05		
Compactive Effort	Standard	Standard		
Moisture Variation (%)	1.0 dry	0.5 dry		
Hilf Density Ratio (%)	97.8	95.6		

$\boldsymbol{c}$	m	-	0 m	+-
Cc	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ш	en	เธ





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00468

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 11

Project No.: 3807351.011

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing



K-15. Parte

Accreditation No. 12719
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards. 12712

Approved Signatory: Krushik Patel (Senior Geotechnician)
Date of Issue: 23/02/2018

12712 Date of Issue: 23/02/2018
THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

### Sample Details

Location:

**Client Request ID:** 

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S18DS-01684	S18DS-01685	S18DS-01686
Field Sample ID	1	2	3
Date Tested	16/02/2018	16/02/2018	16/02/2018
E	355339	355334	355325
N	5782208	5782260	5782168
	Layer 3	Layer 3	Layer 1
Soil Description	Clay	Clay	Clay
Depth of Test (mm)	150	150	150
Depth of Layer (mm)	200	200	200
AS Sieve Size (mm)	19.0	19.0	19.0
Field Wet Density (t/m³)	1.97	2.03	1.97
Peak Converted Wet Density (t/m³)	2.01	2.06	2.00
Compactive Effort	Standard	Standard	Standard
Moisture Variation (%)	0.0	1.5 dry	0.5 wet
Hilf Density Ratio (%)	98.0	98.6	98.6





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00496

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 11

Project No.: 3807351.011

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025 – Testing



K-B. Parte

Accreditation No. 12719
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards. 12712

Approved Signatory: Krushik Patel (Senior Geotechnician)
Date of Issue: 23/02/2018

THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

### Sample Details

Location:

**Client Request ID:** 

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S18DS-01760	S18DS-01761	
Field Sample ID	1	2	
Date Tested	19/02/2018	19/02/2018	
E	5782162	5782143	
N	355339	355321	
	Layer 2	Layer 2	
Soil Description	Clay	Clay	
Depth of Test (mm)	150	150	
Depth of Layer (mm)	200	200	
AS Sieve Size (mm)	19.0	19.0	
Field Wet Density (t/m³)	2.04	1.94	
Peak Converted Wet Density (t/m³)	0.00	2.02	
Compactive Effort	Standard	Standard	
Moisture Variation (%)		0.5 dry	
Hilf Density Ratio (%)		96.2	

#### Comments

Sample no S18DS-01760 is converted to MDD due to it exceed its range of moisture variation of AS1289.5.7.1 please refer sample No. s18ds-02247





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: DDR:W18DS00586

Issue No: 1

# **Dry Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 11

Project No.: 3807351.011

Order No.: CG Request No.:

TRN: Lot No.:

Accredited for compliance with ISO/IEC 17025

— Testing



K-15. Parte

Accreditation No. 12719
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards. 12712

Approved Signatory: Krushik Patel (Senior Geotechnician)
Date of Issue: 23/02/2018

THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

### Sample Details

Location:

Client Request ID:

Specification Requirements: Minimum Dry Density Ratio of 95% Standard Compaction

Field Test Procedures: AS 1289.5.8.1

Laboratory Test Procedures: AS 1289.5.1.1, AS 1289.2.1.1, AS 1289.5.4.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite
Material: General Fill

Sample ID	S18DS-02247	
Field Sample ID	1	
Date Tested	19/02/2018	
Location	355339	
	5782162	
	Layer 2	
Soil Description	CLAY	
·		
Depth of Test (mm)	150	
Depth of Layer (mm)	200	
Compactive Effort	AS 1289.5.1.1	
AS Sieve Size (mm)	19.0	
Oversize Wet (%)	0	
Field Moisture Content (%)	26.8	
Field Wet Density (t/m³)	2.04	
Field Dry Density (t/m³)	1.61	
Lab Result from Test No.	S18DS-02247	
Maximum Dry Density (t/m³)	1.61	
Optimum Moisture Content (%)	22.5	
Moisture Ratio (%)	120.5	
Moisture Variation	4.5 wet	
Density Ratio (%)	100.0	

#### Comments

This sample is converted in AS1289.5.1.1 from sample no s18ds-01760 AS1289.5.7.1 due to moisture variation has exceeded its range.





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00547

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

**Project:** Meridian Estate - Stage 11

Project No.: 3807351.011

Order No.: **CG Request No.:** 

TRN: Lot No.: Accredited for compliance with ISO/IEC 17025

— Testing



Accreditation No. 12719 ent are traceable to an/national standards. 12712

Approved Signatory: Krushik Patel (Senior Geotechnician) Date of Issue: 23/02/2018 THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

### Sample Details

Location:

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite Material: General Fill

Sample ID	S18DS-02021	
Field Sample ID	1	
Date Tested	21/02/2018	
E	355306	
N	5782172	
	Layer 1	
Soil Description	Clay	
Depth of Test (mm)	150	
Depth of Layer (mm)	200	
AS Sieve Size (mm)	19.0	
Field Wet Density (t/m³)	1.81	
Peak Converted Wet Density (t/m³)	2.03	
Compactive Effort	Standard	
Moisture Variation (%)	0.0	
Hilf Density Ratio (%)	89.4	





Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

### Report No: HDR:W18DS00591

Issue No: 1

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

**Project:** Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: **CG Request No.:** 

TRN: Lot No.: Accredited for compliance with ISO/IEC 17025

— Testing



Approved Signatory: Krushik Patel

Accreditation No. 12719 ent are traceable to an/national standards. 12712

(Senior Geotechnician) Date of Issue: 26/02/2018 THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

### Sample Details

Location:

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite Material: General Fill

Sample ID	S18DS-02258	S18DS-02259	
Field Sample ID	1	2	
Date Tested	23/02/2018	23/02/2018	
E	355284	355283	
N	5782239	5782185	
	Layer 1	Layer 1	
Soil Description	Clay	Clay	
Depth of Test (mm)	150	150	
Depth of Layer (mm)	200	200	
AS Sieve Size (mm)	19.0	19.0	
Field Wet Density (t/m³)	2.01	2.06	
Peak Converted Wet Density (t/m³)	1.96	2.03	
Compactive Effort	Standard	Standard	
Moisture Variation (%)	2.5 dry	1.5 dry	
Hilf Density Ratio (%)	102.6	101.4	





#### **Dandenong South** ACN 143 009 330

25 Metcalf Street DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

## Report No: HDR:W18DS00662

# **HILF Density Ratio Report**

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

**Project:** Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: **CG Request No.:** 

TRN: Lot No.: NATA

Accredited for compliance with ISO/IEC 17025 – Testing

Approved Signatory: J. A. Smith

dor measurements included in t document are traceable to Australian/national standards. 12712 (Senior Technician)

Date of Issue: THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite Material: General Fill

Sample ID	S18DS-02549			
Field Sample ID	1			
Date Tested	28/02/2018			
E	355235			
N	5782148			
Layer	1			
Soil Description	Clay			
Depth of Test (mm)	150			
Depth of Layer (mm)	200			
AS Sieve Size (mm)	19.0			
Field Wet Density (t/m³)	1.91			
Peak Converted Wet Density (t/m³)	1.97			
Compactive Effort	Standard			
Moisture Variation (%)	2.5 dry			
Hilf Density Ratio (%)	97.0			

# Appendix D: Controlled fill certificates

PROJECT : Lot 1111 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

#### **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

#### **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1112 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

#### **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

#### **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1113 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

#### **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

#### **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1114 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

#### **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

#### **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1115 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

#### **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

#### **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1116 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1117 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1118 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1119 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1120 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1121 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1122 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1123 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1124 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1125 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd D

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1126 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1127 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1128 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.

PROJECT : Lot 1129 CGEO REF: 3807351.011.v2

Meridian Estate Stage 11

Clyde North VIC

CLIENT : Grosvenor Lodge Pty Ltd

PO Box 4136

**DANDENONG SOUTH VIC 3164** 

DATE: : August 2018

## **SUMMARY**

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

## **LIMITATIONS**

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 19<sup>th</sup> December 2017 to the 28<sup>th</sup> February 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Border

Robert Barden Geotechnical Engineer Tim Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



