

REPORT

Level One Inspection and Testing Services

Meridian Estate Stage 13, Lot's 1301, 1302, 1339 and 1340

Prepared for:

Grosvenor Lodge Pty Ltd

October 2018

Our Ref: 3807351.013.v1

Document Control

Title: Level One Inspection and Testing Services										
Date	Version	Description Prepared by: Reviewed by: Authorise								
31-10-18	1	Level One report, 3807351.013.v1	RHB	RHB	TJJC					

Grosvenor Lodge Pty Ltd Chadwick Geotechnics Pty Ltd (FILE) pdf

1 сору

Table of contents

1	Introduction	1
2	Project details	1
3	Geology	2
4	Specification	2
5	Inspection and testing	2
6	Conclusion	3
7	Applicability	4

Appendix A: Density Test Location Plan

Appendix B: Table of field density results

Appendix C NATA endorsed laboratory reports

Appendix D: Controlled fill certificates

1 Introduction

Chadwick Geotechnics Pty Ltd (Chadwick Geotechnics) was engaged by Grosvenor Lodge Pty Ltd, to provide Level 1 Inspection and Testing services for the earthworks within Stage 13 of the Meridian Estate in Clyde North.

2 Project details

The project included the preparation and filling of lot's 1301, 1302, 1339 and 1340. The specification required the earthworks to be completed under Level 1 Supervision that is, full-time Inspection and Testing of the earthworks. Chadwick Geotechnics were onsite for the duration of the earthworks program.

The location of the site is shown in figure 1 below.



Figure 1: Approximate site location (Image sourced from Nearmaps)

3 Geology

Published information¹ shows that the site is underlain by various geologies listed as follows;

- Quaternary Age Unnamed dune deposits Formation (Qd1) comprising of sand, clay and calcareous sand.
- Quaternary Age Unnamed swamp and lake deposits Formation (Qm1) comprising of silt and clay.
- Palaezoic Age Murrindindi Supergroup (Sm) comprising of mudstone and sandstone Neogeone Age Baxter Sandstone Formation (Nxx) comprising of sandstone, conglomerate, siltstone and ironstone.

4 Specification

A summary of the specification is shown below:

Compaction Requirement	95 % Standard Compaction
------------------------	--------------------------

5 Inspection and testing

The inspection and testing of earthworks has been carried out in accordance with AS3798-2007, 'Guidelines on earthworks for commercial and residential developments', with a frequency of field density tests as per a type one project (large scale operation). Compaction control laboratory testing was undertaken in our NATA accredited Dandenong South laboratory in accordance with AS1289 'Methods of Testing Soils for Engineering Purposes'.

Prior to fill being placed the subgrade was inspected. The inspections were performed in accordance with the Level 1 guidelines presented in AS 3798–2007 Section 5.5. No soft spots were encountered during the inspections, the area was found to be firm and free of vegetation and other deleterious material.

Full time Level 1 Inspection and testing of the filling operations commenced on the 18th April 2018 and was completed on the 6th July 2018. During this period Chadwick Geotechnics observed the works, including the supply of material, conditioning of material (moisture conditioning and oversize removal), placement and compaction of the fill material.

All fill material was placed in lift sequences and Chadwick Geotechnics verified that the surface of the stripped area and additional lifts were thoroughly scarified and moisture conditioned prior to placement of additional layers to prevent delamination at the layer interface.

Field density and moisture content testing was carried out using a calibrated nuclear density gauge in accordance with AS 1289.5.8.1. The HILF rapid compaction test was used for peak converted wet density determinations in accordance with AS 1289.5.7.1. Test locations were recorded using a handheld GPS unit. A site plan showing the field density test locations is provided in Appendix A.

A total of six (6) tests were performed during the filling process.

The results show that all tests achieved the specification requirements for the project.

A summary table of Hilf density tests is provided in Appendix B and the laboratory test reports are provided in Appendix C.

¹ BIBBY, L.M., 2004. Simplified 1: 4 000 000 Geology of Victoria. Geological Survey of Victoria Special Publication. GeoScience Victoria.

6 Conclusion

On the basis of our inspections and after considering all test results relating to the project, it is our opinion, so far as it is able to be determined, that:

- The materials used by the earthworks contractor met the geotechnical property requirements of the specification.
- The sourced fill was considered to be natural and clean and suitable for use at the site.
- The fill material placed was tested at a suitable frequency in accordance with AS 3798-2007-Table 8.1 and the results indicate the compacted clay achieved the density requirement of the specification.
- Given the consistent construction practices followed by the earthworks contractor and as witnessed by the Chadwick Geotechnics, combined with the satisfactory verification of test results achieved, it is inferred that areas of the site between test locations were performed to the same standard as those areas that have been tested.

It is our opinion that the earthworks undertaken have been performed in accordance with the requirements of Section 8.2 of AS3798-2007 - Level 1 Inspection and Testing.

7 Applicability

This report has been prepared for the exclusive use of our client Grosvenor Lodge Pty Ltd in good faith and in accordance with the Chadwick Geotechnics quality system for the earthworks filling at the site.

This report is based on the nature of the project and the conditions present in, factors affecting the soil at the time of the inspections, namely the 18th April 2018 to the 6th July 2018. No responsibility or liability will be accepted, and Chadwick Geotechnics is indemnified to the full extent permitted by law in respect of the use of this report where there has been a change in the nature of the project or the conditions on site that may alter or affect the conclusions of this report.

Should you require any further information regarding this report, please do not hesitate to contact the undersigned on (03) 8796 7900.

Chadwick Geotechnics Pty Ltd

Rober Border

Authorised for Chadwick Geotechnics Pty Ltd by:

Robert Barden

Report prepared by:

Timothy Chadwick

Geotechnical Engineer

Project Director

© Chadwick Geotechnics Pty Ltd.

Other than for the exclusive use of our client Grosvenor Lodge Pty Ltd, no part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise, without the prior written permission of Chadwick Geotechnics Pty Ltd.

www.chadwickgeotechnics.com.au

\keysdc\data\rep\live\geo\projects\3807351\13 stage 13\3807351.013.v1 level one report meridian estate stage 13.docx

Appendix A: Density Test Location Plan





ORIGINAL IN

					0.10012				
	DESIGNED DRAWN	KMJA	Oct.18	PROJECT	MERIDIA	N ESTATE -	STAGE 13		
	CHECKED	TUNOT	000.10	TITLE	HILF DEI	NSITY TEST	LOCATION I	PLAN	4
	PRELIMINA	RY DR	AFT	U	NU	CK R	EVI	SIUN	
N COLOUR	APPROVED	D	ATE	SCALE (A3)	1:1000	FIG No.	FIGURE 1		REV 1


Appendix B: Table of field density results



Hilf Summary Table

3807351.013 Meridian Estate Stage 13

Chadwick Geotechnics 25 Metcalf Street Dandenong South VIC 3175





Report No	Sample No	Date	Test Number	Location [E]	Location [N]	Layer	Density Ratio HILF test (%)	Moisture Variation From OMC	Pass / Fail	Remarks
HDR:W18DS01233	4539	18/04/2018	1	355376	5782279	1	103	0.5 dry	Pass	
HDR:W18DS01233	4540	18/04/2018	2	355375	5782251	2	100	0 dry	Pass	
HDR:W18DS01233	4541	18/04/2018	3	355381	5782327	1	97.5	2 dry	Pass	
HDR:W18DS01233	4542	18/04/2018	4	355383	5782358	2	100	2 dry	Pass	
HDR:W18DS01655	6237	1/06/2018	1	355421	5782419	1	100	2 wet	Pass	
HDR:W18DS01655	6238	1/06/2018	2	355425	5782419	2	100	OMC	Pass	
HDR:W18DS01655	6239	1/06/2018	3	355412	5782369	1	102	0.5 dry	Pass	
HDR:W18DS01655	6240	1/06/2018	4	355467	5782360	2	104.5	1.5 dry	Pass	
HDR:W18DS02027	7772	6/07/2018	1	355407	5782242	1	102	2 dry	Pass	
HDR:W18DS02027	7773	6/07/2018	2	355467	5782239	1	98.5	0 dry	Pass	
HDR:W18DS02027	7774	6/07/2018	3	355483	5782168	1	101	2 dry	Pass	

Appendix C NATA endorsed laboratory reports





Dandenong South ACN 143 009 330 25 Metcalf Street DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W18DS01233

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Merdian Estate - Stage 10

Project No.: 3807351.010

Order No.: **CG Request No.:**

TRN: Lot No.: Accredited for compliance with ISO/IEC 17025 – Testing







Approved Signatory: M. Robinson

(Senior Technician) nent are traceable to an/national standards. 12712

Date of Issue: 23/04/2018 THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite Material: General Fill

Sample ID	S18DS-04539	S18DS-04540	S18DS-04541	S18DS-04542	
Field Sample ID	1	2	3	4	
Date Tested	18/04/2018	18/04/2018	18/04/2018	18/04/2018	
E	355376	355375	355381	355383	
N	5782279	5782251	5782327	5782358	
	Layer 1	Layer 2	Layer 1	Layer 2	
Soil Description	Clay	Clay	Sandy Clay	Clay	
Depth of Test (mm)	150	150	150	150	
Depth of Layer (mm)	200	200	200	200	
Field Wet Density (t/m³)	2.01	2.00	1.94	1.91	
Peak Converted Wet Density (t/m³)	1.95	2.01	1.99	1.92	
Compactive Effort	Standard	Standard	Standard	Standard	
Moisture Variation (%)	0.5 dry	0.0	2.0 dry	2.0 dry	
Hilf Density Ratio (%)	103.0	100.0	97.5	100.0	

Comments





Dandenong South ACN 143 009 330

25 Metcalf Street DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W18DS01655

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 12

Project No.: 3807351.012

Order No.: **CG Request No.:**

TRN: Lot No.: Accredited for compliance with ISO/IEC 17025 – Testing







sor the tests, calibrations surements included in this sent are traceable to annational standards. 12712 Senior Geotechnician)

THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location:

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite Material: General Fill

Sample ID	S18DS-06237	S18DS-06238	S18DS-06239	S18DS-06240
Field Sample ID	1	2	3	4
Date Tested	1/06/2018	1/06/2018	1/06/2018	1/06/2018
Location	355421	355425	355412	355467
E	5782419	5782419	5782369	5782360
N	Layer 1	Layer 2	Layer 1	Layer 2
Soil Description	Silty Clay	Silty Clay	Silty Clay	Silty Clay
Depth of Test (mm)	150	150	150	150
Depth of Layer (mm)	200	200	200	200
AS Sieve Size (mm)	19.0	19.0	19.0	19.0
Field Wet Density (t/m³)	1.97	1.95	1.99	2.03
Peak Converted Wet Density (t/m³)	1.97	1.95	1.95	1.95
Compactive Effort	Standard	Standard	Standard	Standard
Moisture Variation (%)	2.0 wet	0.0	0.5 dry	1.5 dry
Hilf Density Ratio (%)	100.0	100.0	102.0	104.5

Comments





Dandenong South ACN 143 009 330

25 Metcalf Street DANDENONG SOUTH, VIC 3175

Ph: +61 3 8796 7900 Fax: +61 3 9706 9431

Report No: HDR:W18DS02027

Issue No: 1

HILF Density Ratio Report

Client: Greenridge Properties Pty Ltd

Address: PO Box 3131

AUBURN VIC 3123

Project: Meridian Estate - Stage 13

Project No.: 3807351.013

Order No.: **CG Request No.:**

TRN: Lot No.: Accredited for compliance with ISO/IEC 17025 – Testing







Approved Signatory: B. Taseski Approved Signal (Senior Technician)

23/07/2018

d/or measurements included in t document are traceable to Australian/national standards. 12712

THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL

Sample Details

Location: Clyde North

Client Request ID:

Specification Requirements: Minimum Hilf Density Ratio of 95% Standard Compaction +- 3% of OMC

Field Test procedures: AS 1289.5.8.1 Laboratory Test procedures: AS 1289.5.7.1

Sampling Method: AS1289.1.2.1 Clause 6.4 (b)

Source: Onsite Material: General Fill

Sample ID	S18DS-07772	S18DS-07773	S18DS-07774		
Field Sample ID	1	2	3		
Date Tested	6/07/2018	6/07/2018	6/07/2018		
E	355407	355467	355483		
N	5782242	5782239	5782168		
	Layer 1	Layer 1	Layer 1		
Soil Description	Clay	Clay	Clay		
Depth of Test (mm)	150	150	150		
Depth of Layer (mm)	200	200	200		
AS Sieve Size (mm)	19.0	19.0	19.0		
Field Wet Density (t/m³)	1.97	1.95	1.94		
Peak Converted Wet Density (t/m³)	1.93	1.98	1.92		
Compactive Effort	Standard	Standard	Standard		
Moisture Variation (%)	2.0 dry	0.0	2.0 dry		
Hilf Density Ratio (%)	102.0	98.5	101.0		

Comments

Appendix D: Controlled fill certificates



PROJECT: Lot No: 1301 Chadwick Geotechnics REF: 3807351.013.v1

: October 2018

Meridian Estate Stage 13

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 18th April 2018 to the 6th July 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Borden .

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 1302 Chadwick Geotechnics REF: 3807351.013.v1

Meridian Estate Stage 13

CLIENT : Grosvenor Lodge Pty Ltd DATE : October 2018

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 18th April 2018 to the 6th July 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Borden .

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT : Lot No: 1339 Chadwick Geotechnics RFF: 3807351.013.v1

Meridian Estate Stage 13

CLIENT : Grosvenor Lodge Pty Ltd DATE : October 2018

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 18th April 2018 to the 6th July 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Borden .

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



PROJECT: Lot No: 1340 Chadwick Geotechnics REF: 3807351.013.v1

: October 2018

Meridian Estate Stage 13

CLIENT : Grosvenor Lodge Pty Ltd DATE

PO Box 4136

DANDENONG SOUTH VIC 3164

SUMMARY

Chadwick Geotechnics Pty Ltd conducted Level 1 inspection and testing, in accordance with Section 8.2 Level 1 inspection and Testing AS3798-2007, Guidelines on earthworks for commercial and residential developments, during the filling of the site.

So far as it is able to be determined, the fill was placed in accordance with the Specification that required a minimum density ratio of 95% of HILF Density (AS1289.5.7.1) to be achieved.

LIMITATIONS

This Certificate has been commissioned for the filling of the area mentioned above. No responsibility or liability will be accepted for the use of this report for any purpose other than that for which Chadwick Geotechnics Pty Ltd was engaged, specifically for Level 1 Inspection and Testing of the structural fill (excluding top soil).

This report is based on the conditions present and factors affecting the soil at the time of inspection, namely the 18th April 2018 to the 6th July 2018. No responsibility or liability will be accepted and Chadwick Geotechnics Pty Ltd is indemnified to the full extent permitted by law in respect of the use of this Certificate where there has been a change in the nature of the project, or in the site conditions since the site testing.

CHADWICK GEOTECHNICS PTY LTD

Rober Borden .

Robert Barden Geotechnical Engineer Timothy Chadwick Project Director

© Chadwick Geotechnics Pty Ltd.

No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, mechanical, photocopying or otherwise other than in accordance with the limitations and for the purpose provided for above.



